Fault / Error / USB Indicator
Battery Charging Indicator
AC Power Indicator
USB Host Port
Charging Output Indicator[1]
Charge Profile / Error Display[2]
Select Charge Profile Button[3]

24AA12083Z0003

Status Bar

Display Panel

IC SERIES

|		
⚠️ **Solid Red** - Charger Fault. See display panel for details.	⏻ **Solid Blue** - AC power available.	
⚠️ **Flashing Amber** - Caution. External error condition. See display panel for details.	🔋 **Flashing Green** - Low state of charge. **Solid Green** - High state of charge.	
⚠️ **Flashing Green** - USB port active. **Solid Green** - Safe to remove USB flash drive.	🔋 **Flashing Green** - High state of charge. **Solid Green** - Charge complete.	

Selecting a Charge Profile

1 Disconnect AC input from the charger, or from the wall outlet. Wait 30 seconds for the input relay to open. *(See Figure 1)*

2 While reconnecting AC input, press and hold the Select Charge Profile Button. Hold the button until Error Indicator is on and Battery Charging Indicator starts flashing.

3 Press and release the Select Charge Profile Button to advance through charging profiles loaded on the charger. The selected charging profile will be displayed up to three times (e.g. "P-0-1-1" for Profile 11). *(See Figure 2)*

4 Once desired charging profile is displayed, press and hold button for 10 seconds to confirm selection and exit Profile Selection Mode. *(See Figure 3)*

5 Press the Select Charge Profile Button to check that the desired profile is selected.

For more information, visit the Delta-Q support page: www.delta-q.com/support/

Figure 1

Figure 2

Figure 3